

CASE FIELD REPORT**Panama City Code Enforcement/Code Enforcement**Assigned
To:
*MacKinnon,
Rick**CE19-244**

Location of Violation:	4036 Kristanna Drive Panama City, FL 32405	APN#
CDBG	Custom Location Field	Custom Field
NO	Property Type: Residential	Sup Approv: Initial review 1-30-19

No Open Violations

Entry Date	Note Action Date	Type	Officer	Note/Activity
01/30/2019 -		Case	*MacKinnon, Rick	Case Status changed to Abated Case - Property Owner abated
01/30/2019 -		Violation	*MacKinnon, Rick	Change violation status from: Open to: Closed
01/30/2019	2019-01-30	Note	*MacKinnon, Rick	Upon in section the roofing debris on the ROW was being picked up by workers and placed into the onsite dumpster.
01/29/2019 -		Case	*MacKinnon, Rick	Case Status changed to Open Case
01/29/2019	2019-01-29	Note	*MacKinnon, Rick	Upon inspection of this property it was noted that the roofing material was dump on the ROW even though they have on site dumpster. A call to the contracting company (WinterFell Construction Company) was made to inform them this was considered illegal dumping. I was informed do to the weather it was delayed being placed in the dumpster and would be taken care of, I informed them I would be back to re-inspect.
01/29/2019 -		Violation	*MacKinnon, Rick	Added: Illegal Dumping
01/29/2019 -		Violation	*MacKinnon, Rick	Added: Maintaining a Nuisance
01/29/2019 -		Case	*MacKinnon, Rick	Initial Case Status New Complaint
01/29/2019 -		Case	*MacKinnon, Rick	Case Opened (Created)

Follow-up**INVESTIGATION:**

Panama City Code Enforcement Code Enforcement File #CE19-244 4036 Kristanna Drive 01/29/2019



Uploaded on: 01/29/2019 - IMG_0936.JPG



Uploaded on: 01/29/2019 - IMG_0937.JPG



Uploaded on: 01/29/2019 - IMG_0938.JPG



Uploaded on: 01/29/2019 - IMG_0939.JPG